




AVX Corporation

CP0402A1880ENTR

Nombor Bahagian:	CP0402A1880ENTR
Pengilang / jenama:	AVX Corporation
Penerangan Produk	RF DIR COUPLER 1.85-1.91GHZ 0402
Helaian data:	PDF CP0402A1880ENTR.pdf
Status RoHS	 Lead percuma / RoHS Compliant
Kapal Dari	Hong Kong
Cara Penghantaran	DHL/Fedex/TNT/UPS/EMS

[PERMINTAAN UNTUK SEBUT HARGA](#)

Imej mungkin perwakilan. Lihat spesifikasi untuk butiran produk.













Spesifikasi CP0402A1880ENTR

NOMBOR BAHAGIAN	CP0402A1880ENTR
PENGLUAR	AVX Corporation
PENERANGAN	RF DIR COUPLER 1.85-1.91GHZ 0402
STATUS STATUS PERCUMA / ROHS STATUS	Lead percuma / RoHS Compliant
LEMBARAN DATA	PDF CP0402A1880ENTR.pdf
PEMBEKAL PERANTI PAKEJ	0402
SIRI	-
KEMBALI KERUGIAN	26dB
POWER - MAX	3W
PEMBUNGKUSAN	Tape & Reel (TR)
PAKEJ / KES	0402 (1005 Metric)
TAHAP SENSITIVITI LEMBAPAN (MSL)	1 (Unlimited)
PENGILANG STANDARD LEAD TIME	10 Weeks
STATUS STATUS PERCUMA / ROHS STATUS	Lead free / RoHS Compliant
PENGASINGAN	-44dB
KEHILANGAN INSERTION	0.25dB
KEKERAPAN	1.85GHz ~ 1.91GHz
PENERANGAN TERPERINCI	RF Directional Coupler PCS 1.85GHz ~ 1.91GHz 20dB 3W 0402 (1005 Metric)
GANDINGAN FACTOR	20dB
JENIS COUPLER	Standard
APLIKASI	PCS

Tag berkaitan

AVX Corporation CP0402A1880ENTR	Pengedar CP0402A1880ENTR	Pembekal CP0402A1880ENTR
Harga CP0402A1880ENTR	Gambar CP0402A1880ENTR	Imej CP0402A1880ENTR
Datasheet PDF CP0402A1880ENTR	Muat turun Datasheet CP0402A1880ENTR	Datasheet CP0402A1880ENTR
Stok CP0402A1880ENTR	Beli CP0402A1880ENTR	Beli AVX Corporation CP0402A1880ENTR
AVX Corporation CP0402A1880ENTR	Pembekal AVX Corporation	Pengedar AVX Corporation
AVX Corporation CP0402A1880ENTR	AVX Corporation [MIL] CP0402A1880ENTR	

Produk Berkaitan

 <p>CP0402A1880DLTR Pengilang: AVX Corporation Penerangan: RF DIR COUPLER 1.85-1.91GHZ 0402 Dalam stok: Out stock RFQ</p>	 <p>CP0402A1950DLTR Pengilang: AVX Corporation Penerangan: RF DIR COUPLER 1.9GHZ 0402 Dalam stok: Out stock RFQ</p>
 <p>CP0402A1890ALTR Pengilang: AVX Corporation Penerangan: RF DIR COUPLER 1.88-1.9GHZ 0402 Dalam stok: Out stock RFQ</p>	 <p>CP0402A1880ELTR Pengilang: AVX Corporation Penerangan: RF DIR COUPLER 1.85-1.91GHZ 0402 Dalam stok: Out stock RFQ</p>
 <p>CP0402A1950CLTR Pengilang: AVX Corporation Penerangan: RF DIR COUPLER 1.9GHZ 0402 Dalam stok: Out stock RFQ</p>	 <p>CP0402A1950BLTR Pengilang: AVX Corporation Penerangan: RF DIR COUPLER 1.9GHZ 0402 Dalam stok: Out stock RFQ</p>
 <p>CP0402A1950ALTR Pengilang: AVX Corporation Penerangan: RF DIR COUPLER 1.9GHZ 0402 Dalam stok: Out stock RFQ</p>	 <p>CP0402A1880DNTR Pengilang: AVX Corporation Penerangan: RF DIR COUPLER 1.85-1.91GHZ 0402 Dalam stok: Out stock RFQ</p>
 <p>CP0402A1880BNTR Pengilang: AVX Corporation Penerangan: RF DIR COUPLER 1.85-1.91GHZ 0402 Dalam stok: Out stock RFQ</p>	 <p>CP0402A1880CNTR Pengilang: AVX Corporation Penerangan: RF DIR COUPLER 1.85-1.91GHZ 0402 Dalam stok: Out stock RFQ</p>
 <p>CP0402A1890ELTR Pengilang: AVX Corporation Penerangan: RF DIR COUPLER 1.88-1.9GHZ 0402 Dalam stok: Out stock RFQ</p>	 <p>CP0402A1880CLTR Pengilang: AVX Corporation Penerangan: RF DIR COUPLER 1.85-1.91GHZ 0402 Dalam stok: Out stock RFQ</p>